


Process ID# 15238

Cadastral Sheet 33C
2/d
Borough of Chaguanas
County of Caroni



Irons A & B were found on the southern edge of the existing wall

See Plan R.H.229

Co-ordinates are UTM zone 20N Naparima Datum +/-5m
obtained by indirect tie to Trig#1125 (see plan R.H.229)
Bearings are U.T.M. grid based on boundary irons found

SCALE 1/500
Distances are in metres

PLAN of certain boundary lines in the Borough of Chaguanas
Surveyed by me, with due authority, in August 2011 for Yardo Bhagan
In accordance with Regulation 25 (1) of the Land Surveyors' Regulations 1998,
I certify that this plan is correct.

Checked by.....
Entered..... Trinidad & Tobago Land Surveyor. 5th September 2011

